

Post Site Inspection

Site Name: NAIMAN CO/CARAVAN I.D. Number OHD981957913
Date of Inspection: AUG 25, 87

Was Work Plan Followed
If no, explain briefly:

☒ Y ☐ N

Were Samples Collected?
Residential Wells Sampled?

☒ Y ☐ N
☐ Y ☒ N

Anticipated Analysis Report From:

CRL N/A
CLP 11/4/87

Anticipated SI Completion: 11/30/87

Removal Investigation Recommended
If yes, explain briefly:

Y ☒ N

Unanticipated Problems Encountered
If yes, explain briefly:

Y ☒ N

Follow-up site work necessary
If yes, explain briefly:

Y ☒ N

US EPA RECORDS CENTER REGION 5



548559